

Alkmaar, 9 January 2018

Dear Customers,

I am writing with an update on the technical status of Gas Storage Bergermeer (GSB).

GSB announced limited technical availability on the AGSI website, primarily on the withdrawal side.

The current technical restraints are a result of an internal electrical wiring failure in the heater of one of the two DPCUs, which caused damage to a control panel. The panel is in the process of being reconditioned; and in the meantime, only one DPCU can be used.

As always, technical unavailability will continue to be published under the transparency section of our GSB website.

Customers should request their contractual rights via CDIS messaging.

Best regards,

Tom Eikmans

Commercial Manager TAQA Energy