

Alkmaar, 20 February 2018

Dear Customers,

I am writing with an update on the technical status of Gas Storage Bergermeer (GSB).

Last week GSB announced an initial limited technical availability on the withdrawal side for a prolonged period on the AGSI website. This was a result of the consecutive unavailability of two compressors due to, as it appears today, similar electrical motor issues. These compressors are expected to be in maintenance for a prolonged period.

A third compressor is also currently undergoing maintenance and in the process of rebalancing. This compressor is expected to be back online before the injection season.

Yesterday, an announcement was added to the AGSI website which limited technical availability further. This was the result of an internal electrical failure in one of the two DPCUs. This is currently being investigated and the results are expected by the end of this week. We expect two likely scenarios as a result of the investigation; either a continuation of the current withdrawal levels or a recovery in withdrawal capacity back to similar levels of last week.

As always, technical unavailability will continue to be published under the transparency section of our GSB website.

Customers should request their contractual rights via CDIS messaging.

Best regards,

Tom Eikmans

Commercial Manager TAQA Energy